


FIG. 1

005007" E0662960


[illegible]FIG. 2FIG. 3



INTRACOMFORT
WEB SITE

FIG. 4A

005007" E0662960






FIG. 5
COMPLAINT AGENT

005007" E0667960

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




FIG. 6

COMFORT AREAS




FIG. 7

COMPLAINT CATEGORIES

00500T" E066Z960

005007" E0662960

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

COMPLAINT LOG									
DATE & TIME	COMFORT AREA	COMPLAINT	OCCUPANT ID	AREA TEMP.	HUMIDITY	CO2	SETPOINT	DISCHARGE TEMP.	
08/15/00 1:45 PM	FLOOR 4 WEST	HOT	BAKER, J.	79.0 °F	60% RH	500 PPM	76.0 °F	60.0 °F	
08/15/00 1:40 PM	FLOOR 3 EAST	COOL	POND, J.	68.2 °F	62% RH	461 PPM	75.0 °F	55.0 °F	
08/15/00 9:46 AM	FLOOR 1 LOBBY	HOT	THOMAS, K.	80.6 °F	60% RH	450 PPM	75.0 °F	51.0 °F	
08/15/00 9:30 PM	FLOOR 3 EAST	HUMID	RADLER, D.	73.9 °F	76% RH	475 PPM	74.0 °F	54.0 °F	
08/14/00 4:46 PM	FLOOR 4 WEST	HOT	BAKER, J.	78.8 °F	57% RH	488 PPM	76.0 °F	55.0 °F	
08/14/00 2:16 PM	FLOOR 2 NORTH	COOL	FOX, A.	70.0 °F	61% RH	463 PPM	76.0 °F	55.0 °F	
08/14/00 9:23 PM	FLOOR 1 EAST	DRAFTY	SWIFT, C.	72.9 °F	56% RH	495 PPM	73.0 °F	51.0 °F	

FIG. 8